


870A


3 1/2 DIGITAL DUAL DISPLAY AC CLAMP MULTIMETER OPERATION MANUAL

1. SAFETY INFORMATION

The following safety information must be observed to insure maximum personal safety during the operation at this meter.

- 1.1 Do not operate the meter if the body of meter or the test lead look broken.
- 1.2 Check the main function dial and make sure it is at the correct position before each measurement.
- 1.3 Do not perform resistance, diode and continuity test on a live power system.
- 1.4 Do not apply voltage between the test terminals and test terminal to ground that exceed the maximum limit record in this manual.
- 1.5 Exercise extreme caution when measuring live system with voltage greater than 60V DC or 30V AC.
- 1.6 Keep the fingers after the protection ring when measuring through the test lead.
- 1.7 Change the battery when the symbol “” appears to avoid incorrect data.

2. Panel Layout



- 1) Rotary Switch: use this switch to select functions and ranges.
- 2) Back Light key
- 3) D.HOLD key: In any range, push the key, the present display value will be locked and the " DH " symbol will appear, push it again to exit HOL and the " D H " symbol disappear.
- 4) LCD Display: LCD Dual Display, facilitates reads the data.
- 5) V Input Jack , Ω Input Jack , COM Input Jack

2. SPECIFICATIONS

2.1 GENERAL SPECIFICATIONS


Display: 3 1/2 digit LCD with a max. reading of 1999.

Polarity: Automatic negative polarity indication.

Zero adjustment: Automatic.

Overrange indication: Only the "1" or "-1" display.

Sample rate: 2 times/sec

Low battery indication: “”

Safety Standards: The meter is up to the standards of IEC1010 Double Insulation, Pollution Degree 2, Over voltage Category III.

Data hold: Push the HOLD button and the “DH” sign will appear on the display.

Back light: Push the LIGHT button to light the backlight then it will auto light off after approx. 5 seconds.

Clamp opening size: 45mm.

Operating Environment: Temperature 32 ~ 104 ° F(0 ~ 40 ° C), humidity < 75%RH.

Storage Environment: Temperature -4 ~ 140 ° F(-20 ~ 60 ° C), humidity < 90%RH.

Power supply: 9V Zinc-carbon battery.

Dimension: 225 (L) × 77 (W) × 44 (H) mm

Weight: Approx. 450g (including battery).

2.2 ELECTRICAL SPECIFICATIONS

Accuracies are ±(% of reading + number in last digit) at 23 ± 5 ° C, ≤ 75%RH.

2.2.1 DC Voltage

Range	Accuracy	Resolution
1000V	1.0% of rdg+10digits	1V

Overload protection: 1000V DC/750Vrms AC

Impedance: 10MΩ

2.2.2 AC Voltage

Range	Accuracy	Resolution	Frequency
750V	2.5% of rdg+15 digits	1V	50~100Hz

Average sensing, calibrated to rms of sine wave

Overload protection: 1000V DC/750Vrms AC

Impedance: 10MΩ

2.2.3 AC Current

Range	Accuracy	Resolution	Frequency
20A	2.0% of rdg+20 digits	10mA	50~60Hz
200A	2.0% of rdg+25 digits	100mA	
1000A	0 ~ 800	3.0% of rdg+25 digits	
	800 ~ 1000	5.5% of rdg+25 digits	

Average sensing, calibrated to rms of sine wave


Overload protection: 1000A rms within 60 seconds

2.2.4 Resistance

Range	Accuracy	Resolution
2000Ω	1.2% of rdg+10 digits	1 Ω


Overload protection: 250V DC/250Vrms AC

2.2.5 Diode test

Range	Description	Test condition
	Display read approximately forward Voltage of diode.	Forward DC current approx 1.5mA Reversed DC voltage approximately 3V

Overload protection: 250V DC/250Vrms AC


2.2.6 Audible continuity Test

Range	Description	Test condition
	Built-in buzzer sounds if resistance is less than 80 Ω .	Open circuit voltage approx 3V

Overload protection: 250V DC/250Vrms AC.

3. OPERATION

3.1 DC Voltage Measurement

- 1) Connect the black test lead to "COM" socket and red test lead to the "V" socket.
- 2) Set the selector switch to "1000V " position.
- 3) Measure the voltage by touch the test lead tips to the test circuit where the value of voltage is needed.
- 4) Read the result from the LCD panel.
- 5) Push the HOLD button to lock display value, push it again to exit.
- 6) Push the LIGHT button to light the back light.

3.2 AC Voltage Measurement

- 1) Connect the black test lead to "COM" socket and red test lead to the "V" socket.
- 2) Set the selector switch to "750V \sim " position.
- 3) Measure the voltage by touch the test lead tips to the test circuit where the value of voltage is needed.
- 4) Read the result from the LCD panel.
- 5) Push the HOLD button to lock display value, push it again to exit.
- 6) Push the LIGHT button to light the back light.

3.3 AC Current Measurement

- 1) Set the selector switch to desired "20A \sim " 、 "200A \sim " or "1000A \sim " position.
- 2) Open the clamp by pressing the jaw-opening handle and insert the cable to be measured into the jaw.
- 3) Close the clamp and get the reading from the LCD panel.
- 4) Push the HOLD button to lock display value, push it again to exit.
- 5) Push the LIGHT button to light the back light.

Note:

Before this measurement, disconnect the test lead with the meter for safety.


3.4 Resistance Measurement


- 1) Connect the black test lead to "COM" socket and red test lead to the "Ω" socket.
- 2) Set the selector switch to "2000Ω" position.
- 3) Connect tip of the test leads to the points where the value of the resistance is needed.
- 4) Read the result from the LCD panel.
- 5) Push the HOLD button to lock display value, push it again to exit.
- 6) Push the LIGHT button to light the back light.

Note:

When take resistance value from a circuit system, make sure the power is cut off and all capacitors need to be discharged.

3.5 Diode Measurement


- 1) Connect the black test lead to "COM" socket and red test lead to the "Ω " socket.

- 2) Set the selector switch to "  " position.
- 3) Connect the test leads across the diode under measurement, display shows the approx. forward voltage of this diode.
- 4) Push the HOLD button to lock display value, push it again to exit.
- 5) Push the LIGHT button to light the back light.

Note:

Make sure the power is cut off and all capacitors need to be discharged under this measurement.


3.6 Audible Continuity Test

- 1) Connect the black test lead to "COM" socket and red test lead to the "Ω" socket.
- 2) Set the selector switch to "  " position.
- 3) Connect the test leads to two point of circuit, if the resistance is lower than approx. 80 Ω , the buzzer sounds .
- 4) Push the HOLD button to lock display value, push it again to exit.
- 5) Push the LIGHT button to light the back light.

Note:

Make sure the power is cut off and all capacitors need to be discharged under this measurement.

4. Battery replacement

- 1) When the battery voltage drop below proper operation range the  "symbol will appear on the LCD display and the battery need to be changed.
- 2) Before changing the battery, set the selector switch to "OFF". Open the cover of the battery cabinet by a screwdriver.
- 3) Replace the old battery with the same type battery.
- 4) Close the battery cabinet cover and fasten the screw.

5. MAINTENANCE

- 1) Before open the battery door, disconnect both test lead and never uses the meter before the battery door is closed.
- 2) To avoid contamination or static damage, do not touch the circuit board without proper static protection.
- 3) If the meter is not going to be used for a long time, take out the battery and do not store the meter in high temperature or high humidity environment.
- 4) When take current measurement, keep the cable at the center of the clamp will get more accurate test result.
- 5) Repairs or servicing not covered in this manual should only by qualified personal.
- 6) Periodically wipe the case with a dry cloth and detergent. Do not use abrasives or solvents on this instruments.
- 7) Please take out the battery when not using for a long time.

Above picture and content just for your reference. Please be subject to the actual products if anything different or updated. Please pardon for not informing in advance.